

Example 1: Phase Plot

$$KG(j\omega) = \frac{2}{j\omega} \cdot \left(\frac{j\omega}{0.5} + 1 \right) \cdot \frac{1}{\left(\frac{j\omega}{10} + 1 \right) \left(\frac{j\omega}{50} + 1 \right)}$$

