
Is Full State Feedback Always Available?

In a typical system, measurements are provided by sensors:



Full state feedback u = -Kx is not implementable!!