

Timeline

- 5.55 pm: Explosion in H1 Houston DC
 - Short circuit in transformer set it on fire
 - Caused an explosion of battery-acid fumes from UPS backup
 - (Cascading failures)
 - Blew out 3 walls of first floor