

Scale Convention for Bode Plots

	magnitude	phase
horizontal scale	log	log
vertical scale	log	linear

Advantage of the scale convention: we will learn to do Bode plots by starting from simple factors and then building up to general transfer functions by considering products of these simple factors.