

Pole Placement by State Feedback

General procedure for any *controllable* system:

1. Convert to CCF using a suitable invertible coordinate transformation T (such a transformation exists by controllability).
2. Solve the pole placement problem in the new coordinates.
3. Convert back to original coordinates.